



Altro Walkway™ 20 / VM20 | VM20 SD | VM20 Plus

Technical information

| | | | |
|--|--|--|--------------------------------|
| | Fire behaviour tested CHF value Smoke value | AS/ISO 9239.1-2003 7.3 kW/m ² 7.3% kW/m ² 6.4 kW/m ² 160%. min 160%. min 56%. min | |
| | Slip resistance Wet pendulum slip Oil-wet inclining platform | AS/NZS 4586 - 2013 Appendix A AS/NZS 4586 - 2013 Appendix D | P3 R10 |
| | Sound insulation | EN ISO 10140-8 | ca. 5 dB |
| | Flooring type | EN 651 | Safety flooring |
| | Thickness | EN ISO 24346 | 2 mm |
| | Wear layer thickness | EN ISO 24340 | 2 mm |
| | Roll dimensions | EN ISO 24341 | 2 m x 20 m = 40 m ² |
| | Weight | EN ISO 23997 | 2.6 kg/m ² |
| | Residual indentation | EN ISO 24343-1 | ≤ 0.10 mm |
| | Classification for use | EN ISO 10874 | 34, 42 |
| | Flexibility | EN ISO 24344 | Pass |
| | Dimensional Stability | EN ISO 23999 | ≤ 0.4 % |
| | Light fastness | EN ISO 105-BO2 | ≥ 6 |
| | Castor chair abrasion | EN 425 | Yes, type W |
| | Wear resistance | EN 13845 Annex D | ≤ 10% / 50000 cycles |
| | Chemical resistance | EN ISO 26987 | Good |
| | Under floor heating | EN 12524 | Suitable |
| | Electrical behaviours | EN 1815 | ≤ 2 kV Antistatic |
| | VOC emissions | CDPH 1350 / Floorscore Indoor Air Comfort Gold | Approved Approved |

Altro Walkway 20 | 07 | Altro Limited, Works Road, Letchworth Garden City, Herts, SG6 1NW, UK | EN 13845 | Dop-No.1001 | Reaction to fire: Bfl-s1 | Slip resistance: DS | EN 14041:2004/AC:2006 | 1029 Resilient floor covering to be used within a building

Altro Walkway 20SD | 07 | Altro Limited, Works Road, Letchworth Garden City, Herts, SG6 1NW, UK | EN 13845 | Dop-No.1017 | Reaction to fire: Bfl-s1 | Slip resistance: DS | Electrical Behaviour (Dissipative): ≤109 Ohms | | EN 14041:2004/AC:2006 | 1029 | Resilient floor covering to be used within a building



*Information sur le niveau d'émission de substances volatiles dans l'air intérieur, présentant un risque de toxicité par inhalation, sur une échelle de classe allant de A+ (très faibles émissions) à C (fortes émissions).



Sustainability



Installation and maintenance

Please refer to Altro installation and maintenance instructions. Failure to follow these instructions can affect product performance. Some materials are known to cause staining on vinyl floors. Typical examples include: asphalt and bitumen materials, cardboard / hardboard (wet), dyes from printed literature or packaging, rubber-backed carpets and rubber mats and rubber furniture rests and trolley wheels. Technical information on installation and staining can be found at www.altro.com/au

Altro, Designed for possibilities. Made for people. Altro Walkway™ 20 / VM20 | VM20 SD | VM20 Plus and Altro Easyclean Technology are trademarks of Altro Limited.

For further information:

Australian head office +61 3 9764 7000
Sales and stock inquiries info@asf.com.au
Technical Services technical_apac@altro.com