




the future is safer with altro

Altro Fortis Titanium™

Wall and door protection / Protección para paredes y puerta / Wand- und Türenschtutz




Pearl FT/41
LRV83



Mustard FT/222
LRV69



Riviera FT/207
LRV64



Almond FT/32
LRV70



Tan FT/206
LRV41



Battleship FT/208
LRV43



Denim FT/201
LRV32



Cardinal FT/221
LRV13



Kingfisher FT/213
LRV22



Oxford FT/211
LRV10

Light Reflectance Values measured in accordance with BS8493:2008.
Valor de reflectancia de la Luz medido de acuerdo con Betc.
Lichtreflexions-Werte gemessen gemäß BS8493:2008.


Exact material match with samples cannot be guaranteed.
No podemos garantizar que el material del suelo de seguridad coincida exactamente con el de las muestras.
Eine exakte Übereinstimmung des Materials mit Mustern kann nicht garantiert werden.

Codes: **LRV** = Light Reflectance Value.
Códigos: **LRV** = Valor de reflectancia de la Luz.
Code: **LRV** = Lichtreflexions-Wert.



Altro Fortis Titanium

More than just walls / Mas que paredes / Mehr als nur Wände



i Technical information / Información técnica / Technische Informationen

Density Densidad Dichte (g/cm ³)	Gardener impact resistance Resistencia a los impactos Gardner Schlagfestigkeit (in-lb)	Impact resistance Resistencia a los impactos Schlagfestigkeit (KJ/m ²)	Tensile strength Resistencia tensil Zugfestigkeit (MPa)	Shore Hardness Dureza Shore Shore-Härte (D)	Expansion coefficient @ 20°C after 1 hour storage at 90°C Coeficiente de expansión de 20 °C después de 1 h de almacenaje a 90 °C Ausdehnungskoeffizient @ 20 °C nach 1 Stunde Lagerung bei 90 °C (10 ⁴ / K)	Fire Performance Resistencia al fuego Verhalten im Brandfall
ISO 1183	ASTM D4226	Charpy ISO 179 / ea	ISO 527	ISO 868	DIN 53752	EN13501
1.39	131	>9	48	79	7x10 ⁻⁵	B-s3-d0

i For further technical information please visit www.altro.com / www.asf.com.au
Si desea obtener más información técnica, visite www.altroscandess.com
Weitere technische Informationen finden Sie unter www.altro.de



+44 (0) 1462 707 700

www.altro.com

enquiries@altro.com

+34 91 549 5230

www.altroscandess.com

suelos@altroscandess.com

+49 (0) 40 51 49 49 22

www.altro.de

anfrage@altro.de



! Installation and Maintenance / Instalación y manutención / Installation und Instandhaltung

Altro Fortis Titanium must be handled and installed according to Altro's guidelines.

For further information or technical advice, contact:

+ 44 (0)1502 561364 + 44 (0) 1502 531461 enquiries@altro.com

Los revestimientos para paredes Altro WhiteRock deben utilizarse e instalarse según indicaciones de Altro. Para obtener información adicional o asesoría técnica

+ 34 91 549 52 30 +34 91 544 03 76 suelos@altroscandess.com

Altro Fortis Titanium muss anhand der Altro Richtlinien gehandhabt und installiert werden. Weitere Informationen und technische Beratung erhalten Sie unter:

+49 (0) 40 51 49 49 22 +49 (0)40 51 49 49 49 anfrage@altro.de