



Stain + chemical resistance report

Altro Puraguard

Chemical	Concentration	Temp.	Resistant
Α			
Bleach			
Butane		20	Ø
Chlorine water	Saturated	40	Ø
Chlorine water	12° 5	40	Ø
Chlorine water	48%	40	
Citric acid	Up to 20%	40	Ø
Citric acid	Saturated	40	Ø
City gas		20	Ø
Glucose	Saturated	40	
Glycerine	All concentrations	40	•
Hydrogen peroxide	Up to 20%	40	
Hydrogen peroxide	Up to 30%	40	•
Kerosine / petroleum		40	Ø
Oils and greases		40	•
PeridoxRTU®			Ø
Seawater		40	Ø
Soap solution	Fully concentrated	40	Ø
Vegetable tannage extracts	Solution	20	•
Water		40	Ø
Wine, red or white		20	•
Wine vinegar		40	