

SAFETY INFORMATION SHEET Issue No: 16 Date: 01/10/2023

**IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND THE COMPANY** 

PRODUCT NAME: Altro Walkway 20 (VM20 / VM20SD / VMI20)

Altro Reliance 25 (D25) Altro Classic 25 (X25) Altro Atlas 40 (X40)

Altro Impressionist II (IP20) Altro Suprema (SU20/SUI20)

Altro Stronghold 30 (K30) Altro Wood (safety)

Altro Illustra

PRODUCT TYPE/USE: **Vinyl Sheet Flooring** 

**EMERGENCY TEL NOS:** +44 (0)1462 480480, +44 (0)1462 489269

SUPPLIER: ALTRO FLOORS **WORKS ROAD** 

LETCHWORTH GARDEN CITY

HERTS, SG6 1NW, UK TELEPHONE: +44 (0)1462 480480

Email: sds@altro.com

MANUFACTURER: Please contact Altro for details.

COMPOSITION/INFORMATION ON INGREDIENTS

HAZARDOUS INGREDIENTS CAS NO: CONTENT HEALTH **RISK PHRASES** NON-HAZARDOUS

FAX:

HAZARDS IDENTIFICATION

INHALATION: No risk under normal circumstances, but in a major fire PVC may burn; Hydrogen chloride (HCL) is formed. This

will irritate the inhalation system. HCL forms Hydrochloric acid when in contact with water or moisture.

Altro Marine 20 (T20)

Altro ContraX (CX20)

Altro Pisces (SB20)

Altro XpressLay (XL22 / XLI22)

Altro Wood Comfort (safety)

Altro Wood adhesive-free

Altro Illustra adhesive-free

Altro Aquarius (AQ20/AQI20/PX20)

Altro Stronghold 30 / K30 adhesive-free

+44 (0)1462 480010

SKIN CONTACT: No risk under normal circumstances.

**EYE CONTACT:** As for inhalation. If HCL is formed it can react with the moisture in the eyes to form Hydrochloric acid. This will

cause severe irritation to the eves.

INGESTION: May cause choking otherwise it is non-hazardous.

**GENERAL COMMENTS:** If flooring is not maintained as recommended by Altro the safety properties may be affected.

FIRST AID MEASURES

INHALATION: If PVC flooring is ignited move the exposed person to fresh air. If breathing is difficult, properly trained personnel

may assist affected person by administering 100% oxygen. Keep the affected person warm and at rest. Get

prompt medical attention.

SKIN CONTACT: Non-hazardous

**EYE CONTACT:** If PVC flooring is ignited and Hydrochloric acid has formed from the moisture in the eyes; promptly wash eyes

with plenty of water while lifting the eye lids. Continue to rinse for at least 15minutes and get medical attention.

INGESTION: If stuck in throat remove by any means possible. Seek medical attention immediately if choking persists.

**FIRE FIGHTING MEASURES** 

**EXTINGUISHING MEDIA:** Water spray, fog or mist. Foam. Carbon dioxide (CO2).

SPECIAL FIRE FIGHTING PROCEDURES: Self extinguishing but will burn in the presence of flames. HCL is formed, use protection mask for acidic gases.

**HAZARDOUS COMBUSTION PRODUCTS:** Fire creates: Hydrogen chloride (HCL).

**ACCIDENTAL RELEASE MEASURES** 6.

STEPS TO BE TAKEN IF PRODUCT IS

RELEASED OR SPILT:

Non-Applicable

HANDLING AND STORAGE

**USEAGE PRECAUTIONS:** No special precautions are required. Ensure all handling is carried out according to the Kinetic method of lifting. STORAGE PRECAUTIONS:

Rolls of material should be stored in the vertical position and must be restrained using a safety chain or rope.

Store in a clean, dry area. Full rolls weigh in excess of 100Kg.

STORAGE CRITERIA: Non hazardous material storage.

Altro Vinyl Flooring Page 1 of 2



SAFETY INFORMATION SHEET Issue No: 16 Date: 01/10/2023

## 8. EXPOSURE CONTROLS / PERSONAL PROTECTION

INGREDIENT NAME
CAS NO:
STD
LTEL
STEL

ppm
mg/m3
ppm
mg/m3

NON-HAZARDOUS
Image: Case of the control of the

PROTECTIVE EQUIPMENT: None Required

HYGENIC WORK PRACTICES: Maintain the flooring as recommended by Altro.

9. PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE: Up to 2m wide rolls of flooring COLOUR: BOILING POINT (`c, interval): Not applicable Approximately 1.28

ODOUR/TASTE: Typical - low odour VISCOSITY: Solid

SOLUBILITY DESCRIPTION: Not applicable OTHER PHYSICAL DATA: VOC data available from Altro

10. STABILITY AND REACTIVITY

STABILITY: Stable. Avoid: Flame contact

MATERIALS TO AVOID: Ketone solvents

HAZARDOUS DECOMPOSITION PRODUCTS: Toxic gases/vapours/fumes of: Hydrogen chloride (HCL).

11. TOXICOLOGICAL INFORMATION (SYMPTOMS)

OTHER HEALTH EFFECTS: None.

HEALTH WARNINGS: Can cause irritation from the HCL formed when PVC flooring is burning.

ROUTE OF ENTRY: NON-APPLICABLE TARGET ORGANS: NON-APPLICABLE MEDICAL SYMPTOMS: NON-APPLICABLE

11. ECOLOGICAL INFORMATION

BIO ACCUMULATION: Very low potential for bioaccumulation.

DEGRADABILITY:Very slowly biodegradable.ACUTE FISH TOXICITY:Not toxic to aquatic organisms.

12. DISPOSAL CONSIDERATIONS

**DISPOSAL METHOD:** Landfill in accordance with local regulations.

13. TRANSPORT INFORMATION

LABEL FOR CONVEYANCE: None Required

14. REGULATORY INFORMATION

LABEL FOR SUPPLY:None required.RISK PHRASES:Not applicable.SAFETY PHRASES:Not applicable.

15. OTHER INFORMATION

GENERAL INFORMATION: Joints to be welded with PVC weldrod and hot air gun. Provide good ventilation when welding. Observe PPE

regulations.

**REVISION DATE:** 01/10/2023

**INITIALLY GENERATED:** 

The information provided in this safety data sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as guidance for safe handling, use, processing, storage, transportation, disposal and release, and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process unless specified in the text.

Altro Vinyl Flooring Page 2 of 2